


#### **River Dee Restoration**








- Aboyne removal of 3 croys, boulders placed back into the river channel
- Banchory = 10 croys removed and 5 reduced, boulders placed back into the river channel
- Sluie/Commonty = 9 croys to be removed, boulders placed in channel some removed
- Car Bank, Mar Lodge 60m removal of waste and re-connecting flood plain
- Allt an Slugain 350m burn re-alignment (early summer 2016)

### **Banchory**




# **Banchory Croy - BEFORE**



# **Banchory Croy - AFTER**



### Sluie/Commonty



### **Aboyne Croys, River Dee**



# Car Bank, Mar Lodge









#### Other work areas on River Dee.....









