



The Eden Rivers Trust
Dunmail Building
Newton Rigg College
Penrith, Cumbria CA11 0AH

Tel: 01768 866788


office@edenriverstrust.org.uk
www.edenriverstrust.org.uk

Eden Crayfish Project


Funded by the Catchment Restoration Fund
Project reference no: CRF0039 (ST002)

Fixed point photography monitoring of river enhancement project on Howe Beck, a tributary of the River Lyvennet at Crake Trees, Maulds Meaburn, Penrith, Cumbria

Location




Project details



"Reproduced by permission of Ordnance Survey on behalf of HMSO. © Crown Copyright and database right 2012. All rights reserved. Ordnance Survey Licence number 100031001".

Location of fixed point photographs



Fencing and tree planting – general shots of completed work – March 2013

Picture 1. At downstream end looking upstream after completion. NY 62277 16027.



Picture 2. Midsection looking downstream immediately after completion – March 2013.
NY 62277 15902



Picture 3. Upstream end of fencing and tree planting work immediately after completion
– March 2013. NY 62293 15815.



Pond creation

Picture 4. New pond immediately after construction – looking uphill from stream - March 2013. NY 62290 16029



Picture 4. New pond after tree planting – looking uphill away from stream – March 2013. NY 62290 16029



Picture 5. New pond immediately after construction – looking downstream - March 2013.
NY 62242 10612



Picture 5. New pond after tree planting – looking downstream – March 2013.
NY 62242 10612



Re-meandering works

Picture 6. After work - at furthest upstream end of re-meandering works immediately after completion – March 2013. NY 62265 15916



Picture 6. After tree planting - at furthest upstream end of re-meandering works – March 2013. NY 62265 15916



Picture 7. After work - further downstream immediately after completion – March 2013.
NY 62278 15939



Picture 7. After tree planting – March 2013. NY NY 62278 15939.



Picture 8. After work - further downstream immediately after completion – March 2013.
NY 62280 15952



Picture 8. After tree planting – March 2013. NY 62280 15952



Picture 9. After work - further downstream immediately after completion – March 2013.
NY 62286 15978



Picture 9. After tree planting – March 2013. NY 62286 15978

